

# Inspection Photos

API: 05-009-06189

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 10/8/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-009-06189 | Date: 10/8/2019

## Inspection Photos



**Photo 1.** Facing west toward the PW tank and meter shed located adjacent to CR-49 and 575' east of the well. No operator sign installed at the battery site. Corrective actions of the previous inspection were not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06189 | Date: 10/8/2019

## Inspection Photos



**Photo 2.** Corrective actions of the previous inspection were not performed. There is no berm around the 200 bbl tank. There is unused equipment at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06189 | Date: 10/8/2019



## Inspection Photos



**Photo 3.** The meter shed does not appear to be stable and is leaning over which is a safety concern. Corrective actions of the previous inspection were not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06189 | Date: 10/8/2019

## Inspection Photos



**Photo 4.** Facing toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06189 | Date: 10/8/2019



## Inspection Photos



**Photo 5.** There debris and vegetation around the equipment which is a fire hazard. No well sign is posted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06189 | Date: 10/8/2019