

Inspection Photos

ID: 441082

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 10/8/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 441082 | Date: 10/8/2019

Inspection Photos



Photo 1. Facing northeast toward the location. The metal building has been removed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 10/8/2019

Inspection Photos



Photo 2. Facing north toward the location. Soils are compacted and the location has not been reclaimed yet.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 10/8/2019

Inspection Photos



Photo 3. There is a material soil pile at the northwest corner of the location that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 10/8/2019

Inspection Photos



Photo 4. Facing southeast. Unused areas of the location must be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 10/8/2019

Inspection Photos



Photo 5. Facing south at the east side of the location. The pipe risers and cement pads have been removed from this area. There was some debris that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 10/8/2019

Inspection Photos



Photo 6. The gas pipeline remains at the southeast corner. The sign taped on previously is no longer present.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 10/8/2019

Inspection Photos



Photo 7. There is a clean out junction north of the pipeline shown in the previous photo that was associated with the compressor station. The sign is from the former operator and is outdated. The cleanout junction needs to be removed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 441082 | Date: 10/8/2019