

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/07/2019

Submitted Date:

10/07/2019

Document Number:

699300329**FIELD INSPECTION FORM**
 Loc ID 318553 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241578	WELL	PR	03/02/1978	OW	123-09367	JOHN HORST B 1	PR

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Stained soil around WH			
Corrective Action:	For localized stained soils or oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."			Date: 10/22/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Hog fence			
Corrective Action:				Date:
Type	OTHER			
Comment:	Electric transformers and meter box, fabricated steel pipe			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	# 1			corrective date
Comment:	appears to be plumbed to surface			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Electric panel, transformers and meter box			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				

Inspected Facilities

Facility ID: 241578 Type: WELL API Number: 123-09367 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 10/7/2019 at approximately 1215 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the John Horst B #1 KP Kauffman, at API #05-123-09367 in Weld County Colorado. While there, I observed a Producing wellsite.</p> <p>During this inspection the following possible compliance issues were observed: Rule 907.e: Stained soil around the WH. CA date 10/22/2019 see photos #2 and 4. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	10/07/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402202152	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957362
699300330	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957356