

APACHE CANYON 14-03 API# 05-071-06338 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901235



Photo 1: There was no erosion found up gradient of the culvert inlet. This culvert outlet did not have enough drop for the culvert to flow. The culvert outlet had too much vegetation in front of it to flow stormwater out of the culvert. This culvert was removed and a new culvert was installed further up the road.

APACHE CANYON 14-03 API# 05-071-06338 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901235



Photo 2: A new culvert was installed where there was some fill slope on the outlet side, to allow enough drop for the culvert to flow stormwater.

APACHE CANYON 14-03 API# 05-071-06338 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901235



Photo 3: There was enough fill slope for the culvert outlet to be above grade on the outlet side.

APACHE CANYON 14-03 API# 05-071-06338 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901235



Photo 4: The upland watershed is well vegetated upgradient of the new culvert install.

APACHE CANYON 14-03 API# 05-071-06338 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 14, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901235



Photo 5: The upland watershed is well vegetated upgradient of the new culvert install.