

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/07/2019

Submitted Date:

10/08/2019

Document Number:

696101376**FIELD INSPECTION FORM**

Loc ID 310743 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296788	WELL	SI	05/01/2019	OW	123-26908	NORTH PLATTE 43-13	SI

General Comment:

[This is a WELL inspection.](#)
[Well\(s\): 1; Shut-In | SI.](#)
[Battery: Active.](#)

[Centralized Battery serves 2 Location IDs \(310744, 310743\).](#)
[\(Well\(s\): 2; Producing | PR\) ; Well\(s\): 1; Shut-In | SI\).](#)

[Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.](#)

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	WEEDS		
Comment:	Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. See photo #1.		
Corrective Action:	Remove, manage, & control weeds around wellsite. Comply with Rule 603.f.	Date:	10/15/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type:	#		

Comment:	Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.				
Corrective Action:				Date:	
Type: Plunger Lift		# 1			
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.393270,-104.377729	
Comment:	Centralized Battery serves 2 Location IDs (310744, 310743). Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	296788	Type:	WELL	API Number:	123-26908	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: PRODUCTION RECORDS									
<u>Comment:</u> Shut-In. Observed production valves shut. Last production: 04/2019.									
Corrective Action:									
Date:									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 10/07/2019 at approximately 14:08 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte /43-13 Pad Location ID: 310743 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s): 1; Shut-In SI. Battery: Active.</p> <p>Centralized Battery serves 2 Location IDs (310744, 310743). (Well(s): 2; Producing PR) ; Well(s): 1; Shut-In SI).</p> <p>Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issues were observed: 1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 10/15/2019. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/08/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402202247	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957477
696101377	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957476