

Inspection Photos

Operator: Petrox Resources
Location/API #: 007-06215
Date: 10-8-2019



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the southwestern edge facing eastward. Revegetation is progressing in portions with grasses such as western wheatgrass as seen in the foreground, but remains weed infested with Canada and musk thistle, as seen in the background.



Photo 3. View of spilling oil material near the well head. Operator was notified on 10/9/2019 and communicated urgency to address the spill.



Photo 4. View of infestation of Canada thistles in the northern project area. Area needs to be treated and revegetated.



Photo 5. View of musk thistle infestation within the western project area.



Photo 6. View of reference area vegetation comprised of a mosaic of ponderosa pine, gambel oak, and open grass fields.