

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/16/2019

Submitted Date:

10/16/2019

Document Number:

694900591**FIELD INSPECTION FORM**

Loc ID 335301	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: <u>12</u> Number of Comments <u>2</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263215	WELL	PR	09/27/2002	GW	045-08109	COUEY 31-8A2(D32NEB)	PR
263216	WELL	PR	09/16/2002	GW	045-08110	COUEY 32-3B2(D32NEB)	PR
263217	WELL	PR	02/01/2008	GW	045-08111	COUEY 32-5C4(D32NEB)	PR
263219	WELL	SI	10/01/2018	GW	045-08113	COUEY 32-5A2(D32NEB)	SI
263862	WELL	PR	02/01/2008	GW	045-08149	COUEY 29-13(D32NEB)	PR

General Comment:COGCC Inspection Report Summary

On Wednesday 10/16/19 at approximately 2:30 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus D32NEB Pad, at Location # 335301 in Garfield County, Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed:

Debris in tank containment.

Chemical tank at well heads missing labels

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	chemical tank at well heads missing labels		
Corrective Action:	Install correct labels	Date:	11/18/2019

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	2 wood planks in tank containment		
Corrective Action:	remove debris	Date:	11/18/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	centralized containment				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLS	STEEL AST		,
Comment:	centralized containment				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 263215 Type: WELL API Number: 045-08109 Status: PR Insp. Status: PR**Producing Well**Comment: producingCorrective Action: Date: Facility ID: 263216 Type: WELL API Number: 045-08110 Status: PR Insp. Status: PR**Producing Well**Comment: producingCorrective Action: Date: Facility ID: 263217 Type: WELL API Number: 045-08111 Status: PR Insp. Status: PR**Producing Well**Comment: producingCorrective Action: Date: Facility ID: 263219 Type: WELL API Number: 045-08113 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In☐ Temporarily AbandonedReminder: Comment: Corrective Action: Date: Facility ID: 263862 Type: WELL API Number: 045-08149 Status: PR Insp. Status: PR**Producing Well**Comment: producingCorrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Ditches		Gravel				
Berms		Compaction				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900596	694900591	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4965103