

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign is faded not legible.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	10/10/2019

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electrical transformers, breaker panel and meter.Fabricated steel pipe		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Ancillary equipment		# 1		
Comment:	Electrical transformers, breaker panel and meter.			
Corrective Action:			Date:	
Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:	electric motor			
Corrective Action:			Date:	
Bradenhead		# 1		
Comment:	Appears to be plumbed to surface			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240540 Type: WELL API Number: 123-08328 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 10/16/2019 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at Robert Y. Sakata#1 KP Kauffman, at API # 05-123-08328 Weld County Colorado. This is a follow up inspection per Doc. # 699300129 While there, I observed a SI well. Electric panel appears to be shut off. During this inspection the following compliance issue has not been addressed: Signs: At time of inspection wellhead sign is legible but faded. Emergency contact number is barely legible. Install sign to Comply with rule 210.d this issue is delinquent as of CA date 10/10/2019 See attached photo #1 Location is dry, weather is clear. A follow up inspection on this site inspection needs to be conducted to ensure that Corrective Action is addressed to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	10/16/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300372	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4965204