

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/02/2019

Submitted Date:

10/03/2019

Document Number:

687905610

**FIELD INSPECTION FORM**
 Loc ID: 325144 Inspector Name: Stewart, Joseph On-Site Inspection: ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

19 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		inspections@catamountep.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214119	WELL	PR	07/18/2018	GW	067-05429	A H TERRELL 1	PR
438347	WELL	PR	12/05/2017	GW	067-09913	IGW 154	PR

**General Comment:**

Operator was given corrective actions in previous field inspection reports for other locations (doc#'s 687903685, 687903691, 687904515, 687904515, 687904846) for non-compliance and inadequate maintenance of secondary containment. Operator shall submit to COGCC a plan to make all similarly constructed containment structures (thin liner with used tires) on locations within COGCC jurisdiction (not Indian surface and/or mineral) sufficiently impervious and does not require the use of unused equipment, parts, trash or debris (tires) to secure liner material. Liner appears to be inadequate thickness (8-10mil) and does not function properly evident by numerous holes and tears at this location and others cited. This plan should include self inspection and maintenance schedules to ensure conditions do not recur. Operator shall also demonstrate how tanks are adequately grounded and constructed to minimize the build up of static electricity consistent with industry standards such as API 2003 and NFPA 77 and COGCC Rule 605.a Note: API RP 2003 4.5.6.3 states "The use of sheet plastic should be avoided where flammable vapor might be present". Operator should submit documentation as attachments via FIRR. Plan due as soon as possible, no corrective action time is given to remove unused equipment, trash and debris from containment due to operator being cited for same conditions previously at other locations, operator should notify COGCC when location is ready for re-inspection. Refer all questions to Field Inspection Supervisor Steve Labowskie.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Sign posted at each wellhead.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Labels/placards posted on 500 bbl tank with NFPA flammability rating as "1"			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Company contact information posted. Missing local emergency services number or "911" on all signs. See photo #'s 1,2.			
Corrective Action:	Update sign information per Rule 210.			Date: 11/09/2019
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Ancillary equipment	# 1			corrective date
Comment:	Sound panels on AH Terrell 1.			
Corrective Action:				Date:
Type: Deadman # & Marked	# 6			
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 2			
Comment:	Standard size.			
Corrective Action:				Date:
Type: Flow Line	# 5			
Comment:	AH Terrell 1: 1-3" flowline from wellhead to separator. 1-2" flowline from separator to pumpjack engine fuel gas. 1-2" flowline from separator dump valve to 500bbl produced water tank. 1-3" flowline from separator to meter house. 1-3" flowline from meter house to offsite dogleg.			
Corrective Action:				Date:
Type: Vertical Heated Separator	# 2			
Comment:				
Corrective Action:				Date:

Type: Prime Mover	# 2	
Comment:	Natural gas engines on pumping units.	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:	On separator stacks.	
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Wellheads with block valve assembly installed.	
Corrective Action:		Date:
Type: Flow Line	# 5	
Comment:	IGW 154: 1-3" flowline from wellhead to separator. 1-2" flowline from separator to pumpjack engine fuel gas. 1-2" flowline from separator dump valve to 500bbl produced water tank. 1-3" flowline from separator to meter house. 1-3" flowline from meter house to offsite dogleg.	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	PVC bradenhead access.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Secondary containment poly tarp liner has multiple tears and holes in liner base and on walls. See photo #'s 6,7. Secondary containment has tires in it used to weight down poly tarp liner. See photo #'s 4,5,8.			
Corrective Action:	Remove all unused equipment, parts, trash and debris from secondary containment and use adequate material or engineering to make secondary containment sufficiently impervious in order to comply with Rules 605.a(4) and 906.d			Date:

**Venting:**

Yes/No	NO
Comment:	

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 214119 Type: WELL API Number: 067-05429 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 438347 Type: WELL API Number: 067-09913 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil tanks.
Compaction	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Berms	Pass	Compaction	Pass			
Gradient Terraces	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402207761	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961727">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961727</a>
687905621	AH Terrell 1 Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961705">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961705</a>