

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2019

Submitted Date:

10/11/2019

Document Number:

687905644**FIELD INSPECTION FORM**Loc ID 312073 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		inspections@catamountep.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214163	WELL	TA	04/01/2017	GW	067-05482	OLSON MESAVERDE GAS UNIT 1	TA

General Comment:[Site inspection and equipment inventory with photos at the end of this report.](#)

Location					
Lease Road:					
Type	Access				
comment:	Gravel access road.				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	Sign posted at wellhead.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Company contact information posted. Missing local emergency services number or "911" on all signs				
Corrective Action:	Update sign information per Rule 210				Date: 11/11/2019
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type: Flow Line	# 4				corrective date
Comment:	1-2" flowline from wellhead to separator. 1-4" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg. 1-1/2" flowline from dogleg to separator fuel gas.				
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:	Plumbed to surface.				
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:	Gas meter run with inoperable chart recorder.				
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 1				
Comment:	Separator is missing parts and piping and is currently inoperable.				
Corrective Action:					Date:
Type: Ancillary equipment	# 1				
Comment:	Wellhead with block valve assembly installed.				
Corrective Action:					Date:
Type: Bird Protectors	# 1				
Comment:	On separator stack.				
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 214163 Type: WELL API Number: 067-05482 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment:

-Last reported production was December/2009
-Well status changed to SI in January/2010
-Well status changed to TA in September/2013
-Well currently in TA status.
-MIT doc#401926874 test conducted on 1/31/2019

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402207765	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961731
687905645	Update sign information.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961723
687905646	Overview photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961724