

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2019

Submitted Date:

10/09/2019

Document Number:

693501611

FIELD INSPECTION FORM

Loc ID 320427 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10454

Name of Operator: PETROSHARE CORPORATION

Address: 9635 MAROON CIRCLE #400

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	Production Ops Manager
GRIMES, MEGHAN		mgrimes@petrosharecorp.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203733	WELL	PR	03/01/2019	GW	001-09293	BEISEL 42-1	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Access road covered in weeds		
Corrective Action	Comply with rule 603f	Date:	10/16/2019

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around well head and on location.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	10/23/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment : Tubing laying on location.		
Corrective Action:	Comply with rule 603 f	Date:	10/23/2019
Type	WEEDS		
Comment:	Weeds around well site and in and around equipment on production site		
Corrective Action:	Comply with rule 603f	Date:	10/16/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel rod		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with crude oil tank				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Tank and production equipment has flood plain anchoring on equipment				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203733 Type: WELL API Number: 001-09293 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Well and production facility were shut in at time of inspection.Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday October 9, 2019 at approximately 12:13PM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Beisel #42-1</p> <p>Operator: Petro Share Corp</p> <p>API#: 05-001-09293</p> <p>County: Adams</p> <p>While there, I observed Well and production sites</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil: Rule 907 e Corrective action date of 10-23-19 See photos 2,3,4</p> <p>Weeds: Rule 603f Corrective action date of 10-16-19 See photos 1,5,6,7,8</p> <p>Unused equipment: Rule 603 f Corrective action date of 10-23-19</p> <p>Weather conditions: Partly cloudy and dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	10/09/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402207289	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961266
693501612	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961261