

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2019

Submitted Date:

10/11/2019

Document Number:

696101411

FIELD INSPECTION FORM

Loc ID 456482 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270375	WELL	TA	06/22/2015	GW	123-21882	HUCK 41-28	PA

General Comment:

This is an Alternate Method Inspection | AMI.
Well(s): 1 ; Plugged & Abandoned | PA.
Battery: Shut-down | Inactive.
Inactive Battery SE corner GPS coordinates: 40.376275,-104.434113

Follow-up to Field Inspection Report Doc. #696101378 dated 10/07/2019.
This inspection only comprises the mitigation of prior inspection 1 of 2 Corrective Actions.
Photo provided by Operator.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: Abandoned flow line riser at wellsite has NOT been marked or Locked-out Tagged-out. Refer to Rule 603.f. Mark & Lock-out / Tag-out unused flowline riser at wellsite. Comply w/ Rule 603.f. 24 Hrs. Corrective Action date: 10/10/2019.</p> <p>This insp: * Unused flowline riser at wellsite NOW appears to be marked & Locked-out Tagged-out. See photos #1, 2. Photo # 2 provided by Operator.</p>		
Corrective Action:		Date:	

Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: Unused Equipment at Plugged & Abandoned wellsite & Inactive battery site. a.) Unused well casing head, well guard observed at Plugged & Abandoned wellsite. b.) Unused production equipment at Inactive battery site. ALL Equipment at battery site unused. (Tanks, separator, ECD, gas meter run, risers, & fencing). Refer to Rule 603.f. * Remove ALL unused equipment at wellsite & battery site. Comply w/ Rule 603.f. 30 Days. Corrective Action date: 11/08/2019. Original Corrective Action date remains applicable. See photos #1, 3.</p>		
Corrective Action:	Remove ALL unused equipment at wellsite & battery site. Comply w/ Rule 603.f. 30 Days.	Date:	11/08/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 270375 Type: WELL API Number: 123-21882 Status: TA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well appears to be Plugged & Abandoned | PA.
Casing appears to be cut & capped.
Form 6 Doc # 402100961 indicates cut / cap date: 07/03/2019. Approval Pending.
This is an AMI inspection.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 10/11/2019 at approximately 15:45 hrs. I, Bret Evins, conducted an Alternate Method Inspection AMI at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: Huck /41-28 Pad Location ID: 456482 Well Name: Huck 41-28 API: 05-123-21882 Location County: Weld County, Colorado Weather: Dry</p> <p>Observations from prior on-site inspection: Well(s): 1 ; Plugged & Abandoned PA. Battery: Shut-down Inactive. Inactive Battery SE corner GPS coordinates: 40.376275,-104.434113</p> <p>Follow-up to Field Inspection Report Doc. #696101378 dated 10/07/2019. This inspection only comprises the mitigation of prior inspection 1 of 2 Corrective Actions. Photo provided by Operator.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Abandoned flow line riser at wellsite has NOT been marked or Locked-out Tagged-out. Refer to Rule 603.f. Mark & Lock-out / Tag-out unused flowline riser at wellsite. Comply w/ Rule 603.f. 24 Hrs. Corrective Action date: 10/10/2019. * Unused flowline riser at wellsite NOW appears to be marked & Locked-out Tagged-out. See photos #1, 2. Photo # 2 provided by Operator.</p> <p>During this inspection, the following prior possible compliance issues appear to be NOT addressed: 1.) Unused Equipment at Plugged & Abandoned wellsite & Inactive battery site. a.) Unused well casing head, well guard observed at Plugged & Abandoned wellsite. b.) Unused production equipment at Inactive battery site. ALL Equipment at battery site unused. (Tanks, separator, ECD, gas meter run, risers, & fencing). Refer to Rule 603.f. * Remove ALL unused equipment at wellsite & battery site. Comply w/ Rule 603.f. 30 Days. Corrective Action date: 11/08/2019. Original Corrective Action date remains applicable. See photos #1, 3.</p> <p>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>10/11/2019</p>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402207775	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961770

696101412	AMI: Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961769
-----------	------------------	---