

Inspection Photos
Operator: Catamount Energy
Location/API #: 007-06137
Date: 10-8-2019



Photo 1. View of the project area from the northern entrance facing center. Equipment stored throughout the project area.



Photo 2. View of stained soils approximately 8 feet x 8 feet within the northern project area.



Photo 3. View of bare and eroding soils on the eastern cut-slope, not stabilized.



Photo 4. View of soil stockpile in the northeastern project area. Bare soil is not sufficiently protected/stabilized.



Photo 5. View of equipment stored in the interim reclamation area, needs to be removed and decompaction/revegetation will be needed after removal.



Photo 6. View of reference area vegetation comprised of a mosaic of ponderosa pine, juniper, gambel oak, and open grass fields.