

# Inspection Photos

Operator: Catamount Energy  
Location/API #: 007-06322  
Date: 10-8-2019



Photo 1. View of the project area from the northwestern edge of the working area, facing center.





Photo 2. View of the northern project area from the northwestern edge facing eastward.





Photo 3. View of spotted knapweeds (*Centaurea maculosa*) within the eastern project area.





Photo 4. Portion of project area that does not appear needed for production operations and needs to be reclaimed is shaded in green.





Photo 5. View of reference area vegetation comprised of riparian cottonwood forest.