

Inspection Photos
Location Name: McIntyre 1-3 St
Location ID: 312997



Photo 1. Overview of location taken facing north.



Photo 2. Frack tanks without containment and without labels.

Inspection Photos
Location Name: McIntyre 1-3 St
Location ID: 312997



Photo 3. Tubing stored on location, stained soil at wellhead.



Photo 4. Open rathole and stained soil.

Inspection Photos
Location Name: McIntyre 1-3 St
Location ID: 312997



Photo 5. Stained soil at wellhead.



Photo 6. Tubing and equipment stored on location perimeter.

Inspection Photos
Location Name: McIntyre 1-3 St
Location ID: 312997



Photo 7. Incomplete tank labels.



Photo 8. Noxious weeds on location.