

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/01/2019

Submitted Date:

10/18/2019

Document Number:

689803156**FIELD INSPECTION FORM**Loc ID 313140 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10525Name of Operator: SANTA FE NATURAL RESOURCES INCAddress: 4833 FRONT STREET UNIT B 506City: CASTLE ROCK State: CO Zip: 80104**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments8 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
SULLIVAN, MICHAEL	(303) 681-5901	durangopl@earthlink.net	
		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Colby, Lou		lou.colby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260884	WELL	SI	03/26/2012	GW	081-07070	JSR 4-1	SI

**General Comment:**

FIU follow up inspection.

Follow up to inspection from 12/13/2017 document number 689800659. All corrective actions from that report and from reclamation inspection document number 674104493 remain outstanding. All corrective action dates in this report have been carried over from previous inspections.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Road is overgrown, difficult to locate, impassable without a 4wd vehicle with clearance, and has an entrance gate with no lock or latch.		
Corrective Action	L	Maintain and repair access roads.	Date: 10/08/2016
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery. No sign at wellhead.		
Corrective Action:		Install sign to comply with Rule 210.b.	Date: 10/08/2016
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. Previous operator on battery sign.		
Corrective Action:		Install sign to comply with Rule 210.b.	Date: 10/08/2016
<b>Emergency Contact Number:</b>			
Comment:	Sign not posted or information inaccurate. No emergency contact information for current operator on location.		
Corrective Action:		Install sign to comply with Rule 210.	Date: 10/08/2016
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	1 unused 2" steel riser observed at wellhead and 2 unused 2" steel risers observed at gas meter run not marked for abandonment or locked out tagged out. Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:		Comply with Rule 603.f .	Date: 05/30/2017
Type	UNUSED EQUIPMENT		
Comment:	Gas meter run is becoming debris. Electric boxes with switches set to "on".		
Corrective Action:		Comply with Rule 603.f .	Date: 10/18/2019
Type	WEEDS		
Comment:	Noxious and annual weeds on entire location and beginning to migrate off location.		
Corrective Action:		Comply with Rule 603.f .	Date: 09/19/2016
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 8		

Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 260884 Type: WELL API Number: 081-07070 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 11/18/2019

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	265140	1121015	
	264784	1245378	
	264784	1245378	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689803168	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967135">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967135</a>