

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/18/2019

Submitted Date:

10/18/2019

Document Number:

687905667**FIELD INSPECTION FORM**

Loc ID 325490 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214879	WELL	PR	03/01/2019	GW	067-06483	PINE RIVER 2-29 #2	PR

General Comment:

[Site inspection and equipment inventory with photos at the end of this report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel road access through locked gate on forest service road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Labels and placards posted on tanks and on signs on tanks.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign posted at entrance to location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on signs.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused catwalk sitting by wellhead. See photo.			
Corrective Action:	Remove unused equipment per Rule 603.f.			Date: 11/18/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	TANK BATTERY			
Comment:	T-post and hogwire around location.			
Corrective Action:				Date:
Type	LOCATION			
Comment:	Barbed wire fence around location.			
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:	(1) on separator stack and (2) on heated produced water tanks.		
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	1-3" flowline from wellhead to separator. 1-1" flowline from separator to heated produced water tanks fuel gas. 1-2" flowline from separator dump valve to produced water tanks. 1-4" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly installed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	214879	Type:	WELL	API Number:	067-06483	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		Producing.							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass	Ditches	Pass			
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905668	Overview photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967209
687905669	Unused equipment catwalk.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967210