

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/18/2019

Submitted Date:

10/18/2019

Document Number:

696300726

FIELD INSPECTION FORM

Loc ID 421062 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| Kraich, Adam | | adam.kraich@state.co.us | |
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 421061 | WELL | SI | 07/01/2019 | OW | 123-32812 | State 8-60 16-1H | TA |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Tank Battery Sign at Entrance and Wellhead do not reflect current 24 Hour Emergent Contact Info

Corrective Action: Comply with Rule 210.b

Date: 11/18/2019

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unsed Rods and Tubing at Pumping Unit. See photos 4 & 5 | | |
| Corrective Action: | Comply with Rule 603.f. | Date: | 11/18/2019 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Barbed Wire | | |
| Corrective Action: | | Date: | |

| | | | |
|-------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|-------------------------------|----------------------------------|-------|
| Type: Vertical Heater Treater | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Vertical Separator | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bradenhead | # 1 | |
| Comment: | Appears to be plumbed to Surface | |
| Corrective Action: | | Date: |
| Type: Gas Meter Run | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | 300 BBLs | FIBERGLASS AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Shares berm with the Crude Oil Tanks | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 4 | 400 BBLs | STEEL AST | | 40.667830,-104.093010 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |

| | | | |
|------------------------|--|-------|--|
| Corrective Action: | | Date: | |
| <u>Venting:</u> | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| <u>Flaring:</u> | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 421061 | Type: | WELL | API Number: | 123-32812 | Status: | SI | Insp. Status: | TA |
| Idle Well | | | | | | | | | |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned | | | | | | | | | |
| Reminder: _____ | | | | | | | | | |
| Comment: TA | | | | | | | | | |
| Corrective Action: _____ | | | | | | | | | |
| Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday 10/17/2019 at approximately 12:10, I, Inspector Erica Petrie, conducted a Field Inspection at Noble Energy, State 8-6016-1H at Location #421062 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Rods and Tubing at Pumping Unit. See photos 3 & 4. Comply with Rule 603.f. Corrective Action date 11.18.2019</p> <p>Tank Battery Sign at Entrance and Wellhead do not reflect current 24 Hour Emergent Contact Info. See photo 5. Comply with Rule 210.b. Corrective Action date 11.18.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Educational Inspections</p> | petrie | 10/18/2019 |