



*Photo 1 – Vent Installed at E1 Sample Location*



Photo 2 – W2 Location after Backfill



*Photo 3 – Locations N1 and N2 after Backfill*



Photo 4 – W1 Location, 10/10/2019



*Photo 5 – Location W1, 10/11/2019*