

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/18/2019

Submitted Date:

10/18/2019

Document Number:

699300400**FIELD INSPECTION FORM**

Loc ID 318667 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241862	WELL	SI	04/01/2019	GW	123-09653	WILLIAM D. LANSDOWN UNIT C 1	SI

**General Comment:**

## Location

<b>Lease Road:</b>			
Type	Access		
comment:	Weeds overgrown on access road mostly dead		
Corrective Action	Comply with Rule 204	Date:	11/18/2019

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds overgrown around WH now dead		
Corrective Action:	Comply with Rule 603.f	Date:	10/25/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, transformers and meter box		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			



**Inspected Facilities**Facility ID: 241862 Type: WELL API Number: 123-09653 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary

On Friday 10/18/19 at approximately 0930 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at William D. Lansdown unit C #1 KP Kauffman at API #05-123-09653 in Weld County Colorado.

While there, I observed a SI wellsite.

During this inspection the following possible compliance issues were observed:

Rule 204: Weeds overgrown on access road, Repair and maintain lease road. CA date 11/18/2019 see photos #1.

Rule 603.f: Housekeeping weeds growing around WH . CA date 10/25/2019 see photos #2 and 4.

Location is dry, weather is clear.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.

Continuing education COGCC Inspection Report Summary.

This is a summary of inspection report.

revasr

10/18/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300401	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967487">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967487</a>