

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2019

Submitted Date:

10/21/2019

Document Number:

694900617**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
335120 _____ Ramsey, Scott _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: GRIZZLY OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, vanguard		sghan@vnrenergy.com	SR. EH&S
, vanguard		aaxelson@vnrenergy.com	
, vanguard		scollett@vnrenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291271	WELL	PR	11/20/2007	GW	045-14322	GEISKE 43C-26-692	PR
291273	WELL	PR	11/21/2007	GW	045-14323	GEISKE 42A-26-692	PR
291308	WELL	PR	05/09/2013	GW	045-14330	GEISKE 32B-26-692	PR
291314	WELL	PR	11/24/2007	GW	045-14325	GEISKE 32D-26-692	PR
297963	WELL	PR	05/21/2009	GW	045-17004	GEISKE 41B-26-692	PR
297964	WELL	PR	05/21/2009	GW	045-17005	GEISKE 41A-26-692	PR
297965	WELL	PR	05/15/2009	GW	045-17006	GEISKE 42C-26-692	PR
297966	WELL	PR	05/15/2009	GW	045-17007	GEISKE 42D-26-692	PR
297967	WELL	PR	05/15/2009	GW	045-17008	GEISKE 43D-26-692	PR
297968	WELL	PR	05/18/2009	GW	045-17009	GEISKE 32C-26-692	PR
297969	WELL	PR	05/18/2009	GW	045-17010	GEISKE 42B-26-692	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 10/21/19 at approximately 11:30 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at Grizzly Geiski Pad, at location # 3235120 in Garfield County, Colorado.

While there, I observed Normal production operations. All C/A(s) have been completed from FIRR Document # 402183244.

During this inspection the following possible compliance issues were observed:

Signage does not reflect current operator name.

Install correct signage within 90 days.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	All Signage does not reflect current operator name.		
Corrective Action:	Install correct signage within 90 days.	Date:	01/21/2020

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	staining has been removed		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	chemical tanks		
Corrective Action:		Date:	
Type: Bird Protectors	# 14		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 11		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	300 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	2 tanks are in a seperate containment			
Corrective Action:				
Corrective Action:				

Venting:

Yes/No	YES		
Comment:	braden heads are open		
Corrective Action:			
Corrective Action:			

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		
Corrective Action:		

Inspected Facilities						
Facility ID:	291271	Type:	WELL	API Number: 045-14322	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	291273	Type:	WELL	API Number: 045-14323	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	291308	Type:	WELL	API Number: 045-14330	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	291314	Type:	WELL	API Number: 045-14325	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	297963	Type:	WELL	API Number: 045-17004	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	297964	Type:	WELL	API Number: 045-17005	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	297965	Type:	WELL	API Number: 045-17006	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	297966	Type:	WELL	API Number: 045-17007	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:

Facility ID:	297967	Type:	WELL	API Number:	045-17008	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	297968	Type:	WELL	API Number:	045-17009	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	297969	Type:	WELL	API Number:	045-17010	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction		Culverts				
Gravel		Gravel				
Berms		Compaction				
Ditches		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900620	694900617	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4968811