

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2019

Submitted Date:

10/21/2019

Document Number:

694900619

FIELD INSPECTION FORM

Loc ID 335158 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, vanguard		aaxelson@grizzlyenergyllc.com	
, vanguard		sgghan@grizzlyenergyllc.com	SR. EH&S
, vanguard		scollett@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293142	WELL	PR	05/08/2008	GW	045-14908	SNYDER 24A-26-692	PR
293162	WELL	PR	04/26/2008	GW	045-14910	SNYDER 34A-26-692	PR
293163	WELL	PR	05/08/2008	GW	045-14911	SNYDER 24B-26-692	PR
293164	WELL	PR	04/26/2008	GW	045-14912	SNYDER 34B-26-692	PR
293165	WELL	PR	04/23/2008	GW	045-14913	SNYDER 24C-26-692	PR
293166	WELL	PR	05/03/2008	GW	045-14914	SNYDER 34C-26-692	PR
293167	WELL	PR	04/29/2008	GW	045-14915	SNYDER 24D-26-692	PR
293168	WELL	PR	05/07/2008	GW	045-14916	SNYDER 34D-26-692	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 10/21/19 at approximately 1:30 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly snyder Pad, at location # 335158 in Garfield County, Colorado.

While there, I observed Normal production operations.

During this inspection the following possible compliance issues were observed:

Signage does not reflect current operator name.

Install correct signage within 90 days.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	All Signage does not reflect current operator name.		
Corrective Action:	Install correct signage within 90 days.	Date:	01/21/2020

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	chemical tanks		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	OTHER	HEATED STEEL AST		,	
Comment:	2 tanks are not heated all tanks are 375 bbl					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	bradenheads are open		
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	293142	Type:	WELL	API Number: 045-14908	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	293162	Type:	WELL	API Number: 045-14910	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	293163	Type:	WELL	API Number: 045-14911	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	293164	Type:	WELL	API Number: 045-14912	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	293165	Type:	WELL	API Number: 045-14913	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	293166	Type:	WELL	API Number: 045-14914	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	293167	Type:	WELL	API Number: 045-14915	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	293168	Type:	WELL	API Number: 045-14916	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams		Culverts				
Rip Rap						
Ditches		Gravel				
Compaction		Ditches				
Waddles						
Gravel		Waddles				
Slope Roughening						
Sediment Traps						
Berms		Compaction				

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT
Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900621	694900619	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4968813