

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 3: UNMARKED UNUSED RISERS (1, 1" RISER AND 2, 2" RISERS NEAR WELLHEAD).		
Corrective Action:	REMOVE UNUSED RISERS IN ACCORDANCE TO NTO, COMPLY WITH RULE 603.f.	Date:	11/15/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 279387 Type: WELL API Number: 071-08497 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: LAST MIT IN JAN. 2018

Corrective Action: _____ Date: _____

Facility ID: 282171 Type: WELL API Number: 071-08654 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
THIS IS A FOLLOWUP INSPECTION TO INSPECTION DOC#691400087, CORRECTIVE ACTION HAVE NOT BEEN ADDRESSED. (NOTE: THIS IS THE SECOND NOTICE OF THIS CORRECTIVE ACTION IF THESE CORRECTIVE ACTIONS ARE NOT ADDRESSED BY THE NEXT INSPECTION ENFORCEMENT MAY BE CONSIDERED).	beardslt	10/15/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402210687	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963704
695101523	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963686