

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2019

Submitted Date:

10/22/2019

Document Number:

696101450**FIELD INSPECTION FORM**
 Loc ID 331805 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections
MacLaren, Joe		joe.maclaren@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266119	WELL	TA	12/31/2018	GW	123-21329	DOW 41-33	PA

**General Comment:**

This is a PLUGGED & ABANDONED WELL inspection.

Well(s): 1 ; Plugged & Abandoned | PA.

Battery: Shut-down | Inactive.

Centralized Battery formerly served 1 Location ID (331805). (This Location).

Centralized Battery serves 1 Location IDs (423850).

(Well(s): 1 ; Temporarily Abandoned | TA).

Battery SE corner GPS: 40.361146, -104.434408

Refer to Field Inspection Doc. #696101448 and/or Location ID #423850 for Battery / Facility, Equipment info formerly associated with this P&A'd well.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Deadman # & Marked	# 0		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 266119 Type: WELL API Number: 123-21329 Status: TA Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment:

Well appears to be Plugged & Abandoned | PA.  
Casing appears to be cut & capped.  
Form 6 Doc # 402082586 indicates cut / cap date: 06/07/2019. Approval Pending.

\* Improper abandonment of flowline. Disconnected flowline riser NOT Locked-out / Tagged-out | LOTO.  
Refer to Rule 1105.  
Complete flowline abandonments to comply with Rule 1105.  
See photo #1.

Corrective Action: Complete flowline abandonments to comply with Rule 1105.

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: [P&A wellsite reclamation appears progressing.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 10/21/2019 at approximately 15:49 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: North Platte 44-11-28HZ /Facility  Location ID: 331805  Well Name: DOW 41-33  API: 05-123-21329  Location County: Weld County, Colorado  Weather: Dry</p> <p>While there, I observed:  Well(s): 1 ; Plugged &amp; Abandoned   PA.  Battery: Shut-down   Inactive.</p> <p>Centralized Battery formerly served 1 Location ID (331805). (This Location).  Centralized Battery serves 1 Location IDs (423850).  (Well(s): 1 ; Temporarily Abandoned   TA).  Battery SE corner GPS: 40.361146, -104.434408</p> <p>Refer to Field Inspection Doc. #696101448 and/or Location ID #423850 for Battery / Facility, Equipment info formerly associated with this P&amp;A'd well.</p> <p>During this inspection, the following possible compliance issues were observed.  1.) Improper abandonment of flowline. Disconnected flowline riser NOT Locked-out / Tagged-out   LOTO.  Refer to Rule 1105.  Complete flowline abandonments to comply with Rule 1105.  See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/22/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101451	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4969372">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4969372</a>