

**Inspection Photos**  
**Location Name: Falcon Seaboard #3**  
**API: 05-051-06045**



**Falcon Seaboard #3 well head.**



**Stock pile of soil near southwest edge of location.**

**Inspection Photos**  
**Location Name: Falcon Seaboard #3**  
**API: 05-051-06045**



**Impacted soil stock piled along NW edge of location.**



**Insufficient containment for impacted material.**



**Inspection Photos**  
**Location Name: Falcon Seaboard #3**  
**API: 05-051-06045**



**No containment for impacted material along northern edge of stock pile.**



**Off location flow path of Spill/Release Point ID #467789 has been backfilled.**

**Inspection Photos**  
**Location Name: Falcon Seaboard #3**  
**API: 05-051-06045**



**Unknown piles of soil and rock along SE edge of location.**



**Excavated area along NE edge of location.**



**Inspection Photos**  
**Location Name: Falcon Seaboard #3**  
**API: 05-051-06045**



**Above ground replacement dump line anchored by chains to skid steer and secondary containment stairway railing.**



**Replacement above ground dump line.**



**Inspection Photos**  
**Location Name: Falcon Seaboard #3**  
**API: 05-051-06045**



**Excavated area along NE edge of location.**



**Excavated dump line from separators to tank battery.**