

## Inspection Photos

Location Name: NORRIS 44-31 FOLLOWUP

API#: 05-071-08074

INSP. #: 695101578



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos  
Location Name: NORRIS 44-31 FOLLOWUP  
API#: 05-071-08074  
INSP. #: 695101578



**PHOTO 3: Inadequate berms around tank.**  
**Repair or install berms or other secondary containment devices per Rule 605.a.(4). CA DATE 11-23-19.**

**PHOTO 4: THIS TANK DOES NOT APPEAR TO BEING PLUMBED IN OR IN USE. UNUSED EQUIPMENT. REMOVE UNUSED EQUIPMENTN PER RULE 603.f. CA DATE 11-23-19.**

## Inspection Photos

Location Name: NORRIS 44-31 FOLLOWUP

API#: 05-071-08074

INSP. #: 695101578



**PHOTO 5: UNUSED EQUIPMENT. REMOVE  
UNUSED EQUIPMENT PER RULE 603.f. CA  
DATE 11-23-19.**



**PHOTO 6: AREA OF IMPACTED SOIL NEAR ENGINE SKID.  
Properly treat or dispose of oily waste in accordance with  
907.e. CA DATE 11-23-19.**