



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

PHOTO 3 & PHOTO 4: AREA OF IMPACTED SOIL NEAR ORIGINAL WELLHEAD APPEARS TO HAVE LEAKING HYDRAULIC HOSE OR QUICK FITTINGS.

Corrective Action:

Properly treat or dispose of oily waste in accordance with 907.e.

Date: 11/18/2019

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Bradenhead

# 2

Comment:

BOTH ARE PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Deadman # & Marked

# 6

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 2

Comment:

TELEMETRY EQUIPMMENT

Corrective Action:

Date:

**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 276379 Type: WELL API Number: 071-08332 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 278544 Type: WELL API Number: 071-08433 Status: PR Insp. Status: PR

**Workover**

Comment: BAILING SAND

Corrective Action:

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101574	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970502">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970502</a>