

Inspection Photos

Operator: Catamount Energy
Location/API #: 067-09972
Date: 10-16-2019



Photo 1. View of the project area from the southwestern project area facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation is becoming established, with grasses such as intermediate wheatgrass and crested wheatgrass. Portions of the revegetation area remain sparse and weedy, and may need re-seeding if not progressing.



Photo 3. View of the southern project area where desirable vegetation appears to becoming established, but are threatened by dense annual weedy vegetation. Annual weeds need to be managed for successful revegetation.



Photo 4. View of reference area vegetation comprised of sagebrush, gambel oaks, and perennial grasses and forbs representative of the sagebrush shrubland vegetation type.