

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2019

Submitted Date:

10/17/2019

Document Number:

685200638**FIELD INSPECTION FORM**
 Loc ID 306934 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 7125Name of Operator: BEEMAN OIL & GAS LLCAddress: 3401 QUEBEC ST SUITE 9105City: DENVER State: CO Zip: 80207**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mazotti, Joe		ogp-co@comcast.net	
Galloway, Kelly		kgallowaywerc@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280139	WELL	SI	06/01/2019	OW	067-09071	BARBARA 2	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	unlabeled containers no longer present. CA completed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	crude oil stain on side of tank		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	CA completed. Tractor and equipment no longer stored on location		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	CA completed. A few dead weeds blown into inactive pump jack		
Corrective Action:		Date:	
Type	OTHER		
Comment:	trailer improperly storing waste is no longer present. CA completed.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	debris observed by jersey barrier.		
Corrective Action:	remove debris. explain ownership/purpose of jersey barriers.	Date:	11/18/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 1		

Comment:	only one anchor observed, brightly painted but not marked per rule		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	CA completred				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	280139	Type:	WELL	API Number:	067-09071	Status:	SI	Insp. Status:	SI

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: no erosion or materials handling issues observed

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Calm Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHEComment: Conducted FLIR survey with GF-320 camera in normal sensitivity, no detectable gas present at wellhead and associated flowlines, thief hatch or plugs. CA completed.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402212686	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4965368
685200641	CA performed on tank berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4965364
685200642	pumpjack and prod area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4965365
685200643	jersey barrier and debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4965366
685200644	oil seepage down side of tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4965367