

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/08/2019

Submitted Date:

10/17/2019

Document Number:

688500165

FIELD INSPECTION FORMLoc ID 320460 Inspector Name: CANFIELD, CHRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10454

Name of Operator: PETROSHARE CORPORATION

Address: 9635 MAROON CIRCLE #400

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Kirschner, Steven		steven.kirschner@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager
Allison, Rick		rick.allison@state.co.us	
GRIMES, MEGHAN		mgrimes@petrosharecorp.com	Principal Agent
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	Production Ops Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203819	WELL	PA	05/18/2018	GW	001-09379	EHLER 44-4	PA
320460	LOCATION	CL			-	EHLER-61S67W 4SESE	
449320	SPILL OR RELEASE	CL	03/03/2017		-	Oil dump line from separator to tnk Ehler 44-4	CL

General Comment:

Inspection of the location subject to active Remediation Project 12779, closed Remediation Project 10128, & Spill/Release Point ID 449320 was done in response to a complaint from the surface owner (Document 200448186).

LocationOverall Good: ☒

Emergency Contact Number:

Comment: [Sign not posted](#)Corrective Action: [Install sign to comply with Rule 210.b.](#)

Date: 11/15/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Adequate fencing around the location and open excavation. See Photo 1.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 320460 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____

Date: _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
_____	_____	_____	_____

Comments: Erosion BMPs: Inadequate erosion BMPs around the multiple spoil piles at the location. See Photos 2, 3, 4, 5, & 6.

Other BMPs: _____

Corrective Action: Install storm water BMPs to comply with Rule 1002.f

Date: 10/19/2019

Comment: _____**Corrective Action:** _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	<u>203819</u>	Type:	<u>WELL</u>	API Number:	<u>001-09379</u>	Status:	<u>PA</u>	Insp. Status:	<u>PA</u>
Facility ID:	<u>320460</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u></u>
Facility ID:	<u>449320</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u>CL</u>

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Comment	Operator has not submitted any information concerning Remediation Project 12779 since 05/13/2019. The extent of impacts to soil and ground water were not fully delineated as of that time. A total of 16 temporary ground water monitoring wells were installed on and adjacent to the location, a majority of which are located outside of the metal perimeter fence around the disturbed area, i.e. off of the location. Those temporary wells, without locking caps, are potential preferential pathways for contamination of ground water. The excavation was open as of the date of this inspection and has been partially flooded with ground water.			
Corrective Action	Submit Supplemental Form 27 including; GPS coordinates and analytical results for all soil and ground water samples collected subsequent to 05/13/2019. Additionally, the Supplemental Form 27 must provide details on the following activities: Ground water quality monitoring program. Investigation of surface water quality in the wetland adjacent to the north side of the location. Removal of the E&P waste being stored on the location. An updated implementation schedule.			Date: 10/25/2019
Comment				
Corrective Action				Date:
Comment	E&P waste not properly stored, handled, transported, treated, recycled, or disposed of per Rule 907.			
Corrective Action	Contact COGCC Environmental Protection Specialist.			Date: 10/21/2019

Spill/Remediation:

Comment:

Corrective Action: Date: 10/21/2019

Emission Control Burner (ECB): Comment: Pilot: Wildlife Protection Devices (fired vessels): **COGCC Comments**

Comment	User	Date
Surface owner has submitted a complaint (Document 200448186) concerning the subject location and the operator's actions with respect to Remediation Project 12779.	canfieldc	10/17/2019
Multiple residences are located within 135' of the open excavation and spoil piles described in this inspection.		
A wetland is adjacent to the north side of the location.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402213338	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966037
688500166	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966036