

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2019

Submitted Date:

10/17/2019

Document Number:

696101430**FIELD INSPECTION FORM**Loc ID 332237 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Brian		bjames@hpres.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271412	WELL	PR	07/01/2019	GW	123-22021	SIEBRING 41-32	PR
430337	TANK BATTERY	AC			-	Siebring Pad 5-63-32-16H	AO

General Comment:

This is a WELL & BATTERY inspection.

Well(s): 1 ; Producing | PR.

Battery: Active

Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267).

(Well(s): 5 ; 2: Producing | PR ; 1: Shut-In | SI ; 2: Temporarily Abandoned | TA).

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Methanol		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency number NOT posted at wellsite. Refer to Rule 210.b. (30 Days). * Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 11/18/2019. See photo #1.		
Corrective Action:	* Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 11/18/2019. See photo #1.		Date: 11/18/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by earth berms		

Corrective Action:		Date:	
Equipment:		corrective date	
Type: Other	# 2		
Comment:	2: Unused & unmarked vertical risers near gas meter runs. Valves are shut and plugged. Refer to Rule 603.f regarding marking / LOTO requirements for unused risers. See photos #3, 4.		
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface		
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:	Removed		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Containers: 1: Methanol w/ drip containment. Placarded.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:		Shares berms w/ crude oil tanks.				
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLS	STEEL AST		40.363010,-104.450910	
Comment:		Equalizer lines connect creude oil tanks.				
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:		Shares berms w/ produced H2O tank.				
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	271412	Type:	WELL	API Number:	123-22021	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		Producing PR.							
Corrective Action:								Date:	
Facility ID:	430337	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	AO

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 10/17/2019 at approximately 14:01 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: SIEBRING /41-32 Location ID: 332237 Well Name: Siebring 41-32 API: 05-123-22021 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s): 1 ; Producing PR. Battery: Active Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267). (Well(s): 5 ; 2: Producing PR ; 1: Shut-In SI ; 2: Temporarily Abandoned TA).</p> <p>During this inspection, the following possible compliance issues were observed. 1.) Emergency number NOT posted at wellsite. Refer to Rule 210.b. (30 Days). * Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 11/18/2019. See photo #1.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/17/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402213845	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966457
696101431	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966453