

**KP Kauffman - COGCC Inspection Photos**  
**Location: Nessu 1 Flowline Release**  
**Spill ID # 468756**



**View of fluid release up-slope (looking North East)**



**View of fluid release down gradient (looking South West)**

**KP Kauffman - COGCC Inspection Photos**  
**Location: Nessu 1 Flowline Release**  
**Spill ID # 468756**



**Close up view of pooled fluid (primarily crude oil) on surface**



**View of excavation work being completed by KPK personnel at Spill ID #468756 on 10/21/2019.**

**KP Kauffman - COGCC Inspection Photos**  
**Location: Nessu 1 Flowline Release**  
**Spill ID # 468756**



**View of off location flowlines exposed in excavation (1.5" PVC gas supply line & 3" fiberglass wellhead flowline); looking SW**



**Close up view of failure identified on 3" fiberglass flowline (spiral type fracture).**