

**Inspection Photos**  
**Location Name: Shideler-66S92W 32NESW Pad**  
**Location ID: #334837**  
**Inspection Date: October 15, 2019**



**Photo #1 – Sign located at entrance of location needs repair.**



**Photo #2 – View of tank battery sign and tank battery, from northwest.**



## Inspection Photos

Location Name: Shideler-66S92W 32NESW Pad

Location ID: #334837

Inspection Date: October 15, 2019



**Photo #3 – View of damaged condensate AST from west.  
Note top blown off tank and metal berm damaged (red circle).**



**Photo #4 – Flowline risers and damaged equipment located northeast of tank (1).**





## Inspection Photos

Location Name: Shideler-66S92W 32NESW Pad

Location ID: #334837

Inspection Date: October 15, 2019



**Photo #5 - Flowline risers and damaged equipment located northeast of tank (2).**



**Photo #6 – View of (1) horizontal and (4) vertical separators from south.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Shideler-66S92W 32NESW Pad

Location ID: #334837

Inspection Date: October 15, 2019



**Photo #7 – View of stained area of heated horizontal separators (NE side).**



**Photo #8 – Hydrocarbon odors observed in vicinity of staining on heated horizontal separators.**



## Inspection Photos

Location Name: Shideler-66S92W 32NESW Pad

Location ID: #334837

Inspection Date: October 15, 2019



**Photo #9 – Unused equipment (black conduit) located northeast of separators.**



**Photo #10 – Overview of wellheads, from southeast.**



## Inspection Photos

Location Name: Shideler-66S92W 32NESW Pad

Location ID: #334837

Inspection Date: October 15, 2019



**Photo #11 – Localized accumulations of oil-stained soil beneath wellhead for Graham 32-12A.**



**Photo #12 – Sign at wellhead from previous photo.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources