

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2019

Submitted Date:

10/24/2019

Document Number:

693801196

FIELD INSPECTION FORM

Loc ID 316804 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10453
Name of Operator: PARADOX UPSTREAM LLC
Address: PO BOX 220
City: NATURITA State: CO Zip: 81422

Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Miller, Mandy	970-739-3786	mandym@paradoxresources.com	
Labowskie, Steve		steve.labowskie@state.co.us	
Hankins, Neil	970-428-2742	davidh@paradoxresources.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232822	WELL	PR	07/01/2019	OW	113-06011	MCINTYRE CANYON UNIT 6-H-18	PR

General Comment:

COGCC staff performed a followup field inspection on 10/23/2019. Followup to inspection doc#680403676 on 08/24/2018. Issues were found requiring corrective action. CA from previous inspection completed. See inspection text and photos for details.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	
Type	Main		
comment:			
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	435-587-2237		
Corrective Action:		Date:	_____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused catwalk section inside tank berms		
Corrective Action:	Comply with Rule 603.f .	Date:	12/09/2019
Type	UNUSED EQUIPMENT		
Comment:	Flow line risers not LO/TO or marked are considered unused equipment. See photos for details.		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser.	Date:	10/25/2019
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	
Equipment:			
Type: Flow Line	# 1		corrective date

Comment:	Flowline riser with blind flange. CA from previous inspection completed.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs			38.078719,-108.998523
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 232822 Type: WELL API Number: 113-06011 Status: PR Insp. Status: PR

Producing Well

Comment: [Well returned to production.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: Lat: 38.079023 Long: -108.998871

Reference Point: SE Other: _____ Length: 50 Width: 40

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: Dry

Corrective

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693801200	Inspection photos 10/23/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4972422