

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 1 – Pumping Unit, weeds



Photo 2 – Tank Battery



Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699




Photo 3 – Stained Oil at engine and unused equipment



Photo 4 – PBV Concrete vault is missing Content and Capacity

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 5 – 300 BBL Tank missing Content and Capacity, NFPA label is fading.



Photo 6 – Weeds at Separator

