

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/17/2019

Submitted Date:

10/18/2019

Document Number:

696101438

**FIELD INSPECTION FORM**
 Loc ID 332236 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
James, Brian		bjames@hpres.com	All Inspections
Brown, Tim		tbrown@hpres.com	MIT
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271413	WELL	TA	01/01/2019	GW	123-22020	SIEBRING 42-32	TA

**General Comment:**

This is a WELL inspection.

Well(s): 1 ; Temporarily Abandoned | TA.

Battery: Active

Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267).

(Well(s): 5 ; 2: Producing | PR ; 1: Shut-In | SI ; 2:Temporarily Abandoned | TA).

 Refer to Field Inspection Doc. #696101430 and/or Location ID #332237 for Battery /  
 Facility, Equipment info.

Location					
<b>Lease Road:</b>					
Type	Access				
comment:	Adequate				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Emergency number NOT posted at wellsite. Refer to Rule 210.b. (30 Days). * Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 11/18/2019. See photo #1.				
Corrective Action:	* Post Emergency number at wellsite. Comply w/ Rule 210.b.				Date: 11/18/2019
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	WELLHEAD				
Comment:	Iron panel				
Corrective Action:					Date:
<b>Equipment:</b>					
					corrective date
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:					Date:
Type:	#				
Comment:	Refer to Field Inspection Doc. #696101430 and/or Location ID #332237 for Battery / Facility, Equipment info.				
Corrective Action:					Date:
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.363010,-104.450910

Comment:	Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267). Refer to Field Inspection Doc. #696101430 and/or Location ID #332237 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 271413 Type: WELL API Number: 123-22020 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment:[Temporarily Abandoned | TA.](#)[Last prod: 04/2017.](#)[TA for HZ prep. Form 4 Sundry Notice doc #401544346, Approval Pending.](#)[Form 21-MIT doc #402209203 indicates MIT done: 10/04/2019. Approval Pending.](#)[Reference Form 42 MIT-Notice doc #402186924.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On THU 10/17/2019 at approximately 13:22 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: HIGHPOINT OPERATING CORPORATION  Location Name: SIEBRING-65N63W /32SENE  Location ID: 332236  Well Name: Siebring 42-32  API: 05-123-22020  Location County: Weld County, Colorado  Weather: Dry</p> <p>While there, I observed:  Well(s): 1 ; Temporarily Abandoned   TA.  Battery: Active  Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267).  (Well(s): 5 ; 2: Producing   PR ; 1: Shut-In   SI ; 2:Temporarily Abandoned   TA).</p> <p>Refer to Field Inspection Doc. #696101430 and/or Location ID #332237 for Battery / Facility, Equipment info.</p> <p>During this inspection, the following possible compliance issues were observed.  1.) Emergency number NOT posted at wellsite.  Refer to Rule 210.b. (30 Days).  * Post Emergency number at wellsite.  Comply w/ Rule 210.b.  Corrective Action date: 11/18/2019.  See photo #1.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/18/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402214496	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967110">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967110</a>
696101439	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967108">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967108</a>