

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2019

Submitted Date:

10/18/2019

Document Number:

696101442

FIELD INSPECTION FORMLoc ID 419808 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
Dougherty, Tesla		tesla.dougherty@nblenergy.com	EHS Specialist
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419800	WELL	SI	05/01/2016	OW	123-32357	BASHOR PC AA 17-17	TA

General Comment:

This is a WELL inspection.
Well: Temporarily Abandoned | TA.
Battery: Abandoned & ALL equipment removed.
Abandoned Battery SE corner GPS coordinates: 40.491200, -104.460175
Reclamation progressing.

Abandoned Centralized Battery formerly served 3 Location IDs
(419808, 306261, 306333).
Well(s): 3 ; Temporarily Abandoned | TA.

2nd Follow-up to Field Inspection Doc. #696101344 dated 09/27/2019.
1st Follow-up to Field Inspection Doc. #696100960 dated 05/29/2019.

2 FIRR's have been submitted indicating the unused equipment had been removed when Follow-up inspections confirm unused equipment has NOT been removed.
Reference FIRR doc #402139383 & FIRR doc #402209572.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	<p>Prior 2 insp: Unused equipment (chemical tank) at wellsite. Refer to Rule 603.f. Remove unused chemical tank at wellsite. Comply w/ Rule 603.f. Corrective Action date: 06/28/2019.</p> <p>This insp: This insp: * Unused equipment (chemical tank) remains at wellsite. Original Corrective Action date remains applicable. See photos #1, 2, 3.</p>		
Corrective Action:	Remove unused chemical tank at wellsite. Comply w/ Rule 603.f. Original Corrective Action date remains applicable.		Date: 06/28/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 1	corrective date	
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 419800 Type: WELL API Number: 123-32357 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment:

Temporarily Abandoned | TA.
Battery has been abandoned.
Locked & Tagged-out (LOTO). Orange Decommission tag present.
COGCC records indicate last prod: 04/2016.
SI/TA. MIT requirement waived per variance Doc #401474555. (NOBLE)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 10/18/2019 at approximately 14:11 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: BASHOR PC AA /17-17 Location ID: 419808 Well Name: Bashor PC AA 17-17 API: 05-123-32357 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s): 1 ; Temporarily Abandoned TA. Battery: Abandoned & ALL equipment removed. Abandoned Battery SE corner GPS coordinates: 40.491200, -104.460175 Reclamation progressing. Abandoned Centralized Battery formerly served 3 Location IDs (419808, 306261, 306333). Wells: 3 ; Temporarily Abandoned TA.</p> <p>2nd Follow-up to Field Inspection Doc. #696101344 dated 09/27/2019. 1st Follow-up to Field Inspection Doc. #696100960 dated 05/29/2019.</p> <p>2 FIRR's have been submitted indicating the unused equipment had been removed when Follow-up inspections confirm unused equipment has NOT been removed. Reference FIRR doc #402139383 & FIRR doc #402209572.</p> <p>During this inspection the following possible compliance issues were observed: 1.) Unused equipment (chemical tank) at wellsite. Refer to Rule 603.f. Remove unused chemical tank at wellsite. Comply w/ Rule 603.f. Corrective Action date: 06/28/2019. * Unused equipment (chemical tank) at remains wellsite. Original Corrective Action date remains applicable. See photos #1, 2, 3.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/18/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402214710	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967301
696101443	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4967293