

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2019

Submitted Date:

10/25/2019

Document Number:

693200432**FIELD INSPECTION FORM**Loc ID 334837 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211366	WELL	PR	03/17/1999	GW	045-07126	SHIDELER 32-11	EG
269307	WELL	PR	02/06/2004	GW	045-09349	SHIDELER 32-6C (K32)	EG
269419	WELL	PR	02/05/2004	GW	045-09366	COUEY 32-5A1 (K32)	EG
269420	WELL	PR	02/27/2004	GW	045-09365	GRAHAM 32-12A (K32)	EG
269421	WELL	PR	02/24/2004	GW	045-09367	COUEY 32-5 (K32)	EG

**General Comment:**

COGCC joint inspection with EPS S. Arauza and Western Integrity Inspector R. Murray

Engineering Integrity Inspection performed on October 25, 2019. In response to form 22, document number 402207852.

Corrective actions noted in inspection 698100079, that have not been addressed are still applicable

**Inspected Facilities**

Facility ID: <u>211366</u>	Type: <u>WELL</u>	API Number: <u>045-07126</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>269307</u>	Type: <u>WELL</u>	API Number: <u>045-09349</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>269419</u>	Type: <u>WELL</u>	API Number: <u>045-09366</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>269420</u>	Type: <u>WELL</u>	API Number: <u>045-09365</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>269421</u>	Type: <u>WELL</u>	API Number: <u>045-09367</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

**Flowline**

#1	Type: Dump Line	1 of Lines	
----	-----------------	------------	--

Flowline Description

Flowline Type: Dump Line      Size: 2"      Material: Carbon Steel  
 Variance: No      Age: New      Contents: Multiphase

Integrity Summary

Failures: Other      Spills: No      Repairs Made: Yes  
 Coatings: No      H2S: No      Cathodic Protection: No

Pressure Testing

Witnessed:      Test Result:      Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation    ☒ 1102. Operations, Maintenance, and Repair    ☐ 1103. Abandonment

Comment: Due to accident on location dump line from separator to tank battery was replaced

Corrective Action: Provide pressure test results, performed before returning back to in service, Via FIRR and email to Western Integrity inspector

Date: 11/01/2019

#2	Type: Well Site	9 of Lines	
----	-----------------	------------	--

Flowline Description

Flowline Type: Well Site      Size: 2"      Material: Carbon Steel  
 Variance: No      Age: 5-10 Yrs      Contents: Other

Integrity Summary

Failures:      Spills:      Repairs Made:  
 Coatings:      H2S:      Cathodic Protection:

Pressure Testing

Witnessed:      Test Result:      Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation    ☐ 1102. Operations, Maintenance, and Repair    ☐ 1103. Abandonment

Comment: Unused risers on location have been LOTO, see photos

Corrective Action: Provide annual pressure test data , Via FIRR and email to Western Integrity inspector

Date: 11/01/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200433	Photo 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973594">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973594</a>
693200435	Photo 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973595">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973595</a>