

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/16/2019

Submitted Date:

10/21/2019

Document Number:

688800637

FIELD INSPECTION FORM
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 Hughes, Jim _____ 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Donahue, Jessica	(303) 888-4862	jessica.donahue@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
464354	SPILL OR RELEASE	AC	05/17/2019		-	Hotchkiss Federal 20-12D	EI

General Comment:

On October 16, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Gunnison Energy LLC Spill/Release Point ID #464354. For the most recent field inspection report of this facility, please refer to document #693900451.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	TRASH		
Comment:	Stock piled soil contains what appears to be trash sandbag material.		
Corrective Action:	Comply with Rule 603.f.		Date: 10/31/2019
Type	DEBRIS		
Comment:	Cut off sections of pipe left on site.		
Corrective Action:	Comply with Rule 603.f		Date: 11/21/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Gathering Line	# 2		
Comment:	Steel gas and water gathering lines were exposed in open excavation during this field inspection.		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB):	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	In Process					

Comment: [Excavated material stockpiled along pipeline trench does not have any storm water BMPs.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 11/21/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On October 16, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Gunnison Energy LLC Spill/Release Point ID #464354. For the most recent field inspection report of this facility, please refer to document #693900451. During this inspection an open trench was observed with a replaced section of the water gathering line exposed. The cut out sections of pipe and pipeline debris (wood, sandbag fabric, etc.) were present. Several dead Juniper trees were observed on the downhill side of the ROW, down gradient of the release point.</p>	hughesjo	10/21/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402216389	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4968681
688800638	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4968669