

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/25/2019

Submitted Date:

10/27/2019

Document Number:

679705811

FIELD INSPECTION FORM
 Loc ID 335796 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273860	WELL	PR	04/01/2019	GW	103-10499	PICEANCE CREEK UNIT T87X-3G	PR
273861	WELL	PR	02/01/2017	GW	103-10500	PICEANCE CREEK UNIT T87X-3G1	PR
273862	WELL	PR	03/01/2017	GW	103-10501	PICEANCE CREEK UNIT T87X-3G-2	PR
273863	WELL	SI	08/01/2019	GW	103-10502	PICEANCE CREEK UNIT T87X-3G-3	SI
273864	WELL	SI	05/01/2019	GW	103-10503	PICEANCE CREEK UNIT T87X-3G4	SI
283793	WELL	PR	08/01/2019	GW	103-10718	PICEANCE CREEK UNIT T87X-3G7	PR
283794	WELL	PR	11/01/2013	GW	103-10719	PICEANCE CREEK UNIT T87X-3G5	PR
283795	WELL	PR	06/08/2012	GW	103-10720	PICEANCE CREEK UNIT T87X-3G6	PR
283799	WELL	SI	08/01/2019	GW	103-10721	PICEANCE CREEK UNIT T87X-3G8	SI

General Comment:

COGCC Inspection Report Summary.

On 10-25-2019 at approximately 16:20, inspector Rick Moran, conducted a follow up inspection at XTO Energy wells Piceance Creek Unit T87X in Rio Blanco county of FIR document 679705511.

The following compliance issues were resolved:

- 1) Two unmarked deadman.

This is a summary of inspection report 679705811.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		

Comment:	Two containers of SCI-8760 and 1 container of F 225SW all with secondary containment.			
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:	Inside building.			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Well header.			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		39.901010,-108.257340	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities									
Facility ID:	273860	Type:	WELL	API Number:	103-10499	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	273861	Type:	WELL	API Number:	103-10500	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	273862	Type:	WELL	API Number:	103-10501	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	273863	Type:	WELL	API Number:	103-10502	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	273864	Type:	WELL	API Number:	103-10503	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:	Last recorded production April 2019.								
Corrective Action:						Date:			
Facility ID:	283793	Type:	WELL	API Number:	103-10718	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	283794	Type:	WELL	API Number:	103-10719	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	283795	Type:	WELL	API Number:	103-10720	Status:	PR	Insp. Status:	PR

Producing WellComment: [Producing well on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 283799 Type: WELL API Number: 103-10721 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: [Last recorded production March 2019.](#)

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Compaction	Pass	Compaction	Pass			

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705811	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973773
679705816	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973761