

Inspection Photos
Operator: BP America
Location/API #: 067-05787
Date: 10-22-2019



Photo 1. View of the project area from the eastern corner facing center.



Photo 2. View of the the northern project area from the northeastern corner facing westward.



Photo 3. View of the erosional rilling that continues within the eastern project area.



Photo 4. Downstream view of sediment discharge and bare soils in the eastern project area, where sediment flows off of the well pad, and stabilization is needed.



Photo 5. View of erosional channel within the southeastern project area, continues to erode.



Photo 6. View of reference area vegetation comprised of sagebrush shrubland, largely interspersed with mixed native grasses and forbs.