

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2019

Submitted Date:

10/22/2019

Document Number:

696101450

FIELD INSPECTION FORM

Loc ID 331805 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
,		EHSRC@bonanzacrck.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266119	WELL	TA	12/31/2018	GW	123-21329	DOW 41-33	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1 ; Plugged & Abandoned | PA.
Battery: Shut-down | Inactive.
Centralized Battery formerly served 1 Location ID (331805). (This Location).
Centralized Battery serves 1 Location IDs (423850).
(Well(s): 1 ; Temporarily Abandoned | TA).
Battery SE corner GPS: 40.361146, -104.434408

Refer to Field Inspection Doc. #696101448 and/or Location ID #423850 for Battery / Facility, Equipment info formerly associated with this P&A'd well.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type					corrective date
Deadman # & Marked	# 0				
Comment:					
Corrective Action:					Date: _____

Venting:

Yes/No			
Comment:			
Corrective Action:			Date: _____

Flaring:

Type		
Comment:		
Corrective Action:		Date: _____

Inspected Facilities

Facility ID: 266119 Type: WELL API Number: 123-21329 Status: TA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well appears to be Plugged & Abandoned | PA.
Casing appears to be cut & capped.
Form 6 Doc # 402082586 indicates cut / cap date: 06/07/2019. Approval Pending.

* Improper abandonment of flowline. Disconnected flowline riser NOT Locked-out / Tagged-out | LOTO.
Refer to Rule 1105.
Complete flowline abandonments to comply with Rule 1105.
See photo #1.

Corrective Action: **Complete flowline abandonments to comply with Rule 1105.**

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Comment: <input type="text" value="P&A wellsite reclamation appears progressing."/>						Date: _____
Corrective Action: <input type="text"/>						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 10/21/2019 at approximately 15:49 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte 44-11-28HZ /Facility Location ID: 331805 Well Name: DOW 41-33 API: 05-123-21329 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s): 1 ; Plugged & Abandoned PA. Battery: Shut-down Inactive.</p> <p>Centralized Battery formerly served 1 Location ID (331805). (This Location). Centralized Battery serves 1 Location IDs (423850). (Well(s): 1 ; Temporarily Abandoned TA). Battery SE corner GPS: 40.361146, -104.434408</p> <p>Refer to Field Inspection Doc. #696101448 and/or Location ID #423850 for Battery / Facility, Equipment info formerly associated with this P&A'd well.</p> <p>During this inspection, the following possible compliance issues were observed. 1.) Improper abandonment of flowline. Disconnected flowline riser NOT Locked-out / Tagged-out LOTO. Refer to Rule 1105. Complete flowline abandonments to comply with Rule 1105. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/22/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402217466	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4969376
696101451	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4969372