

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/18/2019

Submitted Date:

10/23/2019

Document Number:

695101560

FIELD INSPECTION FORM

Loc ID 334133 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259033	WELL	SI	07/01/2017	GW	071-07178	BULL FROG 23-7	SI
291208	WELL	PR	10/21/2007	GW	071-09345	BULL FROG 23-7 TR	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 3 & PHOTO 4: UNUSED EQUIPMENT.		
Corrective Action:	REMOVE ALL UNUSED EQUIPMENT FROM LOCATION COMPLY WITH RULE 603.F.	Date:	11/18/2019
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 5 & PHOTO 6: UNUSED EQUIPMENT UNUSED UNMARKED RISERS. TWO 2" RISER AND ONE 1" RISER.		
Corrective Action:	REMOVE ALL UNUSED RISER IN ACCORDANCE WITH NTO.	Date:	12/18/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:			corrective date
Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 2		
Comment:	TR IS PLUMBED TO SURFACE, ORIGINAL WELL IS NOT PLUMBED TO SURFACE		
Corrective Action:		Date:	
Compressor	# 1		
Comment:	COMPRESSOR ON TR WELL.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:

Date:

Inspected Facilities

Facility ID: 259033 Type: WELL API Number: 071-07178 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: MIT PERFORMED, MIT WAS DUE BY AUG. OF THIS YEAR IT IS ABOUT 2.5 MONTHS LATE.
 470 PSI START
 470 PSI @ 5 MIN. AWAY
 470 PSI @ 10 MIN. AWAY
 470 PSI @ 15 MIN. FINAL
 BRADEN HEAD WAS NOT PLUMBED TO SURFACE COULD NOT MONITOR

Corrective Action: _____ Date: _____

Facility ID: 291208 Type: WELL API Number: 071-09345 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402219297	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970509
695101584	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4970497