

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2019

Submitted Date:

10/30/2019

Document Number:

687905713**FIELD INSPECTION FORM**Loc ID 325354 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 74500Name of Operator: REYNOLDS* NOELAddress: BOX 356City: FLORA VISTA State: NM Zip: 87415**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	
Chollett, Shannon		shannon.chollett@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214628	WELL	SI	03/01/1993	GW	067-06232	ESTER (OWP) 1	SI

General Comment:

On 10/29/2019 Joe Stewart with COGCC was onsite with Matt Fogg with Phillips Electric Co. of Durango, Co for disconnection and removal of Ester #1 electric service line from the La Plata Electric Association power pole ID# 6924 to the power panel disconnect on location. LPEA power pole approx. 100' from Southwest corner of location is still live and at time of work conducted, has transformer and meter disconnect still on pole. Photos in attachments section of this report.

Location

Lease Road:			
Type	Access		
comment:	Access is overgrown with sagebrush and grasses. Two-track access to location off of gravel road to adjacent landowner.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	No sign or location marker at site, GIS used to identify location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:	Orange safety fence around open pit for identification and safety.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead with partially buried PVC line to venting pit. Wellhead is not VTA currently and main valve is closed. Pressure gauge on wellhead reads 0psig.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	214628	Type:	WELL	API Number:	067-06232	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Shut-in."/> _____									
Corrective Action: <input type="text"/> _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905714	Electric power disconnect and overview photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977008