



CD-3 CO2 Well Location Photos
API #05-083-06726 / Facility ID #450246
FIR #693900935 / CA #131840 & #131841
FIRR #402227401

CA #131840

Comment: *Interim reclamation is not conducted and was due by October 3, 2019.*

Corrective Action: *Conduct interim reclamation no later than May 1, 2020.*

Response to CA #131840

At the time of the inspection by Catherine Roy on 10/11/2019, interim reclamation at the CD-3 location had already commenced as evidenced by the windrow of 3/4-inch gravel shown in the background of Photo 1 taken during the inspection. Interim reclamation activities commenced on September 30, 2019 at both the CD-3 and CX-14 locations. The comment that reclamation was due by October 3, 2019 is not correct. The drilling rig was released on April 3, 2019 however completion activities did not conclude until April 26, 2019 as stated in the CD-3 Form 5A (Document #402049167). Interim reclamation activities are currently underway and we anticipate completion by December 6, 2019 (weather permitting). Evidence of interim reclamation at the CD-3 location is shown in the photograph below.



Windrowed 3/4-inch gravel on the east side of the CD-3 location

CA #131841

Comment: *Erosional rilling and sediment deposition is occurring along the access road.*

Corrective Action: *Stormwater erosion needs to be controlled along the access road.*

Response to CA #131841

The erosional rills shown in Photo 3 of the inspection report photos are the result of a brief but heavy precipitation event that occurred during the week of September 30, 2019. All erosional rill were raked out during the week of October 14, 2019. Refer to the photos below.





