

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/25/2019

Submitted Date:

10/25/2019

Document Number:

693200432

FIELD INSPECTION FORM

Loc ID 334837 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211366	WELL	PR	03/17/1999	GW	045-07126	SHIDELER 32-11	EG
269307	WELL	PR	02/06/2004	GW	045-09349	SHIDELER 32-6C (K32)	EG
269419	WELL	PR	02/05/2004	GW	045-09366	COUEY 32-5A1 (K32)	EG
269420	WELL	PR	02/27/2004	GW	045-09365	GRAHAM 32-12A (K32)	EG
269421	WELL	PR	02/24/2004	GW	045-09367	COUEY 32-5 (K32)	EG

General Comment:

COGCC joint inspection with EPS S. Arauza and Western Integrity Inspector R. Murray
Engineering Integrity Inspection performed on October 25, 2019. In response to form 22, document number 402207852.
Corrective actions noted in inspection 698100079, that have not been addressed are still applicable

Inspected Facilities									
Facility ID:	<u>211366</u>	Type:	<u>WELL</u>	API Number:	<u>045-07126</u>	Status:	<u>PR</u>	Insp. Status:	<u>EG</u>
Facility ID:	<u>269307</u>	Type:	<u>WELL</u>	API Number:	<u>045-09349</u>	Status:	<u>PR</u>	Insp. Status:	<u>EG</u>
Facility ID:	<u>269419</u>	Type:	<u>WELL</u>	API Number:	<u>045-09366</u>	Status:	<u>PR</u>	Insp. Status:	<u>EG</u>
Facility ID:	<u>269420</u>	Type:	<u>WELL</u>	API Number:	<u>045-09365</u>	Status:	<u>PR</u>	Insp. Status:	<u>EG</u>
Facility ID:	<u>269421</u>	Type:	<u>WELL</u>	API Number:	<u>045-09367</u>	Status:	<u>PR</u>	Insp. Status:	<u>EG</u>

Flowline			
#1	Type: Dump Line	1 of Lines	
<u>Flowline Description</u>			
Flowline Type:	<u>Dump Line</u>	Size:	<u>2"</u>
Variance:	<u>No</u>	Age:	<u>New</u>
		Material:	<u>Carbon Steel</u>
		Contents:	<u>Multiphase</u>
<u>Integrity Summary</u>			
Failures:	<u>Other</u>	Spills:	<u>No</u>
Coatings:	<u>No</u>	H2S:	<u>No</u>
		Repairs Made:	<u>Yes</u>
		Cathodic Protection:	<u>No</u>
<u>Pressure Testing</u>			
Witnessed:		Test Result:	
		Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/>	<u>1101. Installation and Reclamation</u>	<input checked="" type="checkbox"/>	<u>1102. Operations, Maintenance, and Repair</u>
<input type="checkbox"/>		<input type="checkbox"/>	<u>1103. Abandonment</u>
Comment:	<u>Due to accident on location dump line from separator to tank battery was replaced</u>		
Corrective Action:	<u>Provide pressure test results, performed before returning back to in service, Via FIRR and email to Western Integrity inspector</u>		Date: <u>11/01/2019</u>
#2	Type: Well Site	9 of Lines	
<u>Flowline Description</u>			
Flowline Type:	<u>Well Site</u>	Size:	<u>2"</u>
Variance:	<u>No</u>	Age:	<u>5-10 Yrs</u>
		Material:	<u>Carbon Steel</u>
		Contents:	<u>Other</u>
<u>Integrity Summary</u>			
Failures:		Spills:	
Coatings:		H2S:	
		Repairs Made:	
		Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:		Test Result:	
		Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/>	<u>1101. Installation and Reclamation</u>	<input type="checkbox"/>	<u>1102. Operations, Maintenance, and Repair</u>
<input type="checkbox"/>		<input type="checkbox"/>	<u>1103. Abandonment</u>
Comment:	<u>Unused risers on location have been LOTO, see photos</u>		
Corrective Action:	<u>Provide annual pressure test data , Via FIRR and email to Western Integrity inspector</u>		Date: <u>11/01/2019</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402222402	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973596
693200433	Photo 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973594
693200435	Photo 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4973595