

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2019

Submitted Date:

10/28/2019

Document Number:

693200436

**FIELD INSPECTION FORM**Loc ID 334837 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name       | Phone | Email                                 | Comment                                  |
|--------------------|-------|---------------------------------------|--|
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us         | Engineering Integrity Supervisor         |
| Arauz, Steven      |       | steven.arauza@state.co.us             | West Environmental Protection Specialist |
|                    |       | COGCC.inspections@caerusoilandgas.com | All Piceance inspections                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 269421      | WELL | PR     | 02/24/2004  | GW         | 045-09367 | COUEY 32-5 (K32) | EG          |

**General Comment:**

COGCC joint inspection with EPS S. Arauz and Western Integrity Inspector R. Murray

Engineering Integrity Inspection performed on October 25, 2019. In response to form 22, document number 402207852.

Corrective actions noted in inspection 698100079, that have not been addressed are still applicable

## Inspected Facilities

Facility ID: 269421 Type: WELL API Number: 045-09367 Status: PR Insp. Status: EG

## Flowline

|    |                 |            |
|----|-----------------|------------|
| #1 | Type: Dump Line | 1 of Lines |
|----|-----------------|------------|

## Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel  
 Variance: No Age: New Contents: Multiphase

## Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

## Pressure Testing

Witnessed: No Test Result: Charted:

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Due to accident on location dump line from separator to tank battery was replaced

Corrective Action: Provide pressure test results, performed before returning back to in service, Via FIRR and email to Western Integrity inspector

Date: 11/04/2019

|    |                 |            |
|----|-----------------|------------|
| #2 | Type: Well Site | 9 of Lines |
|----|-----------------|------------|

## Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel  
 Variance: No Age: 5-10 Yrs Contents: Multiphase

## Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

## Pressure Testing

Witnessed: Test Result: Charted:

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Unused risers on location have been LOTO, see photos

Corrective Action: Provide annual pressure test data , Via FIRR and email to Western Integrity inspector

Date: 11/04/2019

## Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402223092    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4974090">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4974090</a> |
| 693200437    | Photo 1              | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4974088">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4974088</a> |
| 693200438    | Photo 2              | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4974089">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4974089</a> |