

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2019

Submitted Date:

10/29/2019

Document Number:

699700046

FIELD INSPECTION FORM

Loc ID 316373 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp
Steiner, Nataalie	9706754089	natalie_steiner@xtoenergy.com	Spills
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
468668	SPILL OR RELEASE	AC	10/10/2019		-	SPILL/RELEASE POINT	EI

General Comment:

On October 16, 2019, COGCC Environmental Staff (John Heil) conducted an Environmental field inspection of XTO ENERGY INC (XTO Operator #100264) Location ID 316373 Yellow Creek Federal 3-45-1, Spill ID 468668. Weather was sunny and temperatures about 65 degrees Fahrenheit.

See Inspection Doc# 699700036 for 9/25/2019 Inspection of Spill ID 468668 conducted by COGCC Environmental Staff John Heil.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Location sign knocked down on lease road.		
Corrective Action:	Repair sign to comply with Rule 210.e.	Date:	11/29/2019

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date: <input type="text"/>

Inspected Facilities

Facility ID: 468668 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: COGCC staff observed a 60 feet by 60 feet by 20 feet deep excavation around the point of release (See photos). The Operator was stockpiling the impacted soil on location northwest of the excavation (Approximately 2700 cubic yards). COGCC staff (John Heil) conducted had a meeting with the Operator (Natalie Stiner) in which COGCC staff was informed that historical impacts were discovered while excavating the impacts from Spill 468668.

Corrective Action: Operator shall submit a Form 19 Initial/Supplemental (Spill Type: Historical) with request for closure to address the historical impacts.
 Operator shall submit a Form 19 Supplemental to close the spill under a Form 27.
 Operator shall submit a Form 27 Site Investigation and Remediation Workplan to delineate vertical and horizontal impacts.

Date: 11/29/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402225123	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4975480
699700047	20191016 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4975479