

Construction and Stormwater Inspection

November 4, 2019

Operator: EDGE ENERGY II LLC- #10671

Location ID: 460397

Inspection Document #: 697500776

Weld County, CO

LOT 1 Section 1 T8N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Akbary /1A Pad
Location ID: 460397



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates Operator has installed a vehicle tracking device BMP.



Photo 2. Photo taken from the southwestern location, facing North. Photo illustrates a ditch and berm BMP which has been temporarily stabilized with hydromulch.

Inspection Photos
Location Name: Akbary /1A Pad
Location ID: 460397



Photo 3. Photo taken from the southwestern location, facing North. Photo illustrates the cut slopes have been temporarily tracked with equipment. Note: tracking should be conducted perpendicular to the slopes. Tracking as shown here was done the opposite and would facilitate stormwater flow which would create rills that form gully erosion. Operator shall stabilize the cut slopes for long-term stabilization to comply with site degradation rule 1002.f.

Inspection Photos
Location Name: Akbary /1A Pad
Location ID: 460397



Photo 4. Photo taken from the southern location, facing East. Photo illustrates Operator has temporarily stabilized the top slope (berm) of the cut slope with hydromulch.



Photo 5. Photo taken from the eastern location, facing North. Photo illustrates the topsoil stockpile has been temporarily stabilized with hydromulch and equipment tracking.

Inspection Photos
Location Name: Akbary /1A Pad
Location ID: 460397



Photo 6. Photo taken from the northeastern location, facing East. Photo illustrates a sediment trap installed with a stabilized outlet. Appears the outlet material may have been compromised due to the pipeline installation.

Inspection Photos
Location Name: Akbary /1A Pad
Location ID: 460397



Photo 7. Photo taken from the northeastern location, facing West. Photo illustrates the fill slope has been temporarily stabilized with hydromulch.

Inspection Photos
Location Name: Akbary /1A Pad
Location ID: 460397



Photo 8. Photo taken from the northeastern well pad location, facing East.
Photo illustrates a spill area.