

Location Name: Magpie Operating Inc. – Warnecke – Rem #13484
Inspection Date: 10/21/2019



Photo # 1 – View west across partially backfilled produced water pit



Location Name: Magpie Operating Inc. – Warnecke – Rem #13484
Inspection Date: 10/21/2019



Photo # 2 – View south, pit berms pushed into pit



Location Name: Magpie Operating Inc. – Warnecke – Rem #13484
Inspection Date: 10/21/2019



Photo # 3 – View north, siphon pipe across partial pit dividing berms requires removal, pit berm requires pH, EC and SAR analysis



Location Name: Magpie Operating Inc. – Warnecke – Rem #13484
Inspection Date: 10/21/2019



Photo # 4 – View northeast, siphon pipe across partial pit dividing berms requires removal



Location Name: Magpie Operating Inc. – Warnecke – Rem #13484
Inspection Date: 10/21/2019



Photo # 5 – View north, siphon pipe across partial pit dividing berms requires removal



Location Name: Magpie Operating Inc. – Warnecke – Rem #13484
Inspection Date: 10/21/2019



Photo # 5 – View south, siphon pipe across partial pit dividing berms requires removal, pit berm is not three feet below grade



Location Name: Magpie Operating Inc. – Warnecke – Rem #13484
Inspection Date: 10/21/2019



Photo # 5 – Concrete debris requires removal



Location Name: Magpie Operating Inc. – Warnecke – Rem #13484
Inspection Date: 10/21/2019



Photo # 6 – Former separator area, gravelly soil requires pH, EC and SAR analysis



Location Name: Magpie Operating Inc. – Warnecke – Rem #13484
Inspection Date: 10/21/2019



Photo # 7 – East of former separator area, concrete base and oily bucket require disposal

